



A Higher Level of Reliability



Rope Access Inspection Services from Acuren.

A cost-effective alternative that places safety and quality first.

Acuren’s mission is to provide reliable, repeatable service - for every client, every day. Our rope access inspection services fulfill that promise by providing an alternative way to safely place personnel at your site, delivering accurate and cost-effective inspection results you can trust.

SAFETY	QUALITY	VALUE
<p>Reduce workplace risks, gain big rewards.</p>	<p>Professional NDT inspectors first and foremost.</p>	<p>A cost-effective alternative.</p>
<p>Rely on Acuren’s rope access inspection services to effectively reduce site safety hazards by:</p> <ul style="list-style-type: none"> Eliminating the need to construct and tear-down scaffolding. <ul style="list-style-type: none"> - Reduces the number of people involved on a project. - Reduces length access constraints exist. - Reduces the size of hazard zones. Meeting or exceeding SPRAT guidelines. Providing experienced Level III Rope Access Supervisors on every project. Acuren has logged nearly 100,000 hours of actual rope time without a single recordable injury. 	<p>Acuren’s rope access services deliver accurate, repeatable results:</p> <ul style="list-style-type: none"> Acuren leads the industry in NDT training and techniques, our rope access professionals are highly-qualified inspectors first, rope specialists second. Rope access inspectors are capable of evaluating locations that are unreachable via other access methods, allowing for the examination of any potential failure point. Customers benefit from same high quality, repeatable reporting expected from Acuren. 	<p>Realize measurable cost-savings with Acuren’s rope access services including:</p> <ul style="list-style-type: none"> Save thousands of dollars in scaffolding and crane/manlift rental expenses on each project. Eliminate the productivity costs associated with building and tearing down of scaffolding. Reduce work stoppage costs and slowdown costs with reduced inspection and access constraint time. Reduce risk of failure points in areas too costly or too difficult to inspect using other inspection methods.



Acuren's rope access inspectors can provide a full line of standard, advanced, and specialized NDT/NDE inspection services including (but not limited to):

RT, UT, PT, MT, CR/DR, Real-Time Radiography, Surface ET, AUT, TOFD, Phased Array (PA), Guided Wave (GUL), PMI, and API visual inspection services.



Below are three real-world examples of how Acuren's rope access services have achieved cost savings for our customers:

Petrochemical Industry Customer A:

	Traditional Methods	Acuren Rope Access Methods
Access cost:	\$80,000	none
Inspection:	\$ 1,000	\$10,000
Total cost:	\$81,000	\$10,000
Total time:	8 days	<2 days
	Net savings with Acuren:	\$71,000 (88%)
	Time saved with Acuren:	6+ days

Performed API570 Visual and UT Thickness survey on two overhead lines.

Petrochemical Industry Customer B:

	Traditional Methods	Acuren Rope Access Methods
Access cost:	\$ 39,600	none
Inspection:	\$ 1,200	\$ 9,500
Total cost:	\$ 40,800	\$ 9,500
Total time:	11 days	7 days
	Net savings with Acuren:	\$31,300 (78%)
	Time saved with Acuren:	4 days

Performed UT thickness survey on in-plant piping.

Pulp & Paper Industry Customer A:

	Traditional Methods	Acuren Rope Access Methods
Access cost:	\$ 504,000	none
Inspection:	\$ 30,000	\$ 42,000
Total cost:	\$534,000	\$ 42,000
Total time (Est.): (18 Tank/Silos)	45 days	9 days
	Net savings with Acuren:	\$492,000 (92%)
	Time saved with Acuren:	36+ days

Performed UT thickness survey on ClO2, starch silos, and HD Tanks in tight access location.

Regardless of your location, we have an office nearby ready to serve you. We operate in over eighty locations throughout North America.



US Regional Head Offices

Anchorage

7911 King Street
Anchorage, Alaska, USA
99518
Office 907.569.5000
Fax 907.569.5005

Dayton

705 Albany Street
Dayton, Ohio, USA
45417
Office 937.228.9729
Toll Free 888.228.9729
Fax 937.228.2009

Longview

405 N Eastman Road
Longview, Texas, USA
75601
Office 903.753.2375
Toll Free 800.256.5442
Fax 903.753.6533

Houston

101 Old Underwood Road, BLDG J
La Porte, Texas, USA
77571
Office 281.228.0000
Toll Free: 1.800.853.4417
Fax 281.842.3370

Brookfield

4250 N 126TH Street
Brookfield, Wisconsin, USA
53005
Office 262.781.0105
Toll free: 800.578.7822
Fax 262.781.7796

Canadian Regional Head Offices

Fort McMurray

230 MacDonald Crescent
Fort McMurray, Alberta
Canada
T9H 4B4
Office 780.790.1776
Fax 780.790.9061

Edmonton

7450 - 18th Street
Edmonton, Alberta,
Canada
T6P 1N8
Office 780.440.2131
Toll Free 800.663.9729
Fax 780.440.1167

Vancouver

12271 Horseshoe Way
Richmond, British Columbia
Canada
V7A 4V4
Office 604.275.3800
Toll Free 800.938.3789
Fax 604.274.7235

Toronto

2190 Speers Road
Oakville, Ontario
Canada
L6L 2X8
Office 905.825.8595
Toll Free 877.299.2857
Fax 905.825.8598

